




Stepper Motor 014



Gear Box



Gear 1 is attached directly to the shaft of the motor. 48 steps will turn this 1 time.
Gear 2 (pulled out slightly in the picture to the left) is driven by gear 1 on the “top” end and meshed with gear 3 on the “bottom” end.
Gear 3 is connected to the shaft in which the wheel of the winch is attached.



WINCH

